

Michael O. Leavitt Governor

Robert L. Morgan Executive Director Lowell P. Braxton

Lowell P. Braxton
Division Director
Www.nr.utah.gov

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY

October 16, 2003

TO:

Minerals File

FROM:

Paul Baker, Senior Reclamation Biologist

SUBJECT:

Site Inspection, Cherry Hill Park Mine, Emery Industrial Resources, M/049/021,

Utah County, Utah

Date of Inspection:

October 7, 2003

Time of Inspection:

about 9:15-9:30 a.m.

Conditions:

Clear, 40's

Participants:

Kevin Peacock and Justin Huntington, Nielson Construction; Paul Baker,

DOGM

Purpose of Inspection:

I was passing through the area and decided to make a quick stop and see if there was any reclamation or mining activity.

Observations:

When I arrived at the site, a front end loader was putting material through an operating screen (Photo 1). There was no equipment on site that might be used to haul material off site. The nearest thing to grading equipment was the front end loader.

Conclusions and Recommendations:

The operator has claimed that the screening is being done as part of reclamation, so I did not ask the Nielson Construction personnel to cease operations. Rather, I telephoned and left messages for Wayne Hedberg and Lynn Kunzler to let them know what I had observed and to give them the name and telephone number of Mr. Peacock.

Mr. Peacock told me the screening work was being done for Steve Powell. Nielson Construction had been asked to smooth out the piles as the screening was being done, apparently to help facilitate reclamation. I was told that three truckloads of material had been taken from the site last week for testing purposes. Mr. Peacock said Dan Powell had requested that Nielson Construction crush 50,000 tons of material but that this was not being done.

PB:jb

cc: Dan Powell, operator

O:\M049-Utah\M0490021-CherryHill\inspection\ins-10072003.doc



ATTACHMENT

Photographs M/049/021, Cherry Hill Park Mine, Emery Industrial Resources




Photo 1. Front end loader, screening equipment, and piles of screened material.